Gravois Road Bridge At Gravois Creek

Bridge Replacement Project










Years of moisture have caused extensive deterioration to the underside of the Gravois Creek Bridge.







The concrete on the sides and under the bridge is cracking.



